

TW Series

| | Model # | Compressor Kit Part# | Compressor Plug Part# | Compressor Blanket Part# | Liquid Line Dryer Part# | Capacitor Part# | Contacto Part# | Cond/Evap Water Coil Part# | Expansion Valve Part# | Reversing Valve Part# | Transformer Part# | 2 Step Solenoid Plug Part# | Comfort Alert Module Part# | Term Block or Board Part# | UPM Board Part# | Unit Mounted Controller Part# | Aux Relay Part# | | | |
|------------------------------|---------------|----------------------|-----------------------|--------------------------|-------------------------|-----------------|----------------|----------------------------|-----------------------|-----------------------|-------------------|----------------------------|----------------------------|---------------------------|-----------------|-------------------------------|-----------------|---------------|---------|---------|
| Chiller UPM Board Control | TW025-1CSC | 105-489 | | 641-179 | 562-032 | 860-005 | 700-018 | 601-040 | 300-223 | 850-060 | 500-037 | 603-022 | 641-178 | 641-180 | | | 8 733 800 259 | | 601-009 | |
| | TW025-1CSN | 105-489 | | 641-179 | 562-032 | 860-005 | 700-018 | 601-040 | 300-224 | 850-060 | 500-037 | 603-022 | 641-178 | 641-180 | | | 8 733 800 259 | | 601-009 | |
| | TW035-1CSC | 105-413 | | 641-179 | 562-032 | 860-005 | 700-025 | 601-040 | 300-225 | 850-061 | 500-037 | 603-022 | 641-178 | 641-180 | | | 8 733 800 259 | | 601-009 | |
| | TW035-1CSN | 105-413 | | 641-179 | 562-032 | 860-005 | 700-025 | 601-040 | 300-226 | 850-061 | 500-037 | 603-022 | 641-178 | 641-180 | | | 8 733 800 259 | | 601-009 | |
| | TW049-1CSC | 105-414 | | 641-179 | 562-032 | 860-006 | 700-027 | 601-007 | 300-133 | 850-062 | 500-006 | 603-022 | 641-178 | 641-180 | | | 8 733 800 259 | | 601-009 | |
| | TW049-1CSN | 105-414 | | 641-179 | 562-032 | 860-006 | 700-027 | 601-007 | 300-132 | 850-062 | 500-006 | 603-022 | 641-178 | 641-180 | | | 8 733 800 259 | | 601-009 | |
| | TW061-1CSC | 105-415 | | 641-216 | 562-033 | 860-006 | 700-047 | 601-001 | 300-128 | 850-059 | 500-005 | 603-022 | 641-178 | 641-180 | | | 8 733 800 259 | | 601-009 | |
| | TW061-1CSN | 105-415 | | 641-216 | 562-033 | 860-006 | 700-047 | 601-001 | 300-129 | 850-059 | 500-005 | 603-022 | 641-178 | 641-180 | | | 8 733 800 259 | | 601-009 | |
| | TW071-1CSC | 105-490 | | 641-216 | 562-033 | 860-006 | 700-047 | 601-001 | 300-130 | 850-059 | 500-005 | 603-022 | 641-178 | 641-180 | | | 8 733 800 259 | | 601-009 | |
| | TW071-1CSN | 105-490 | | 641-216 | 562-033 | 860-006 | 700-047 | 601-001 | 300-131 | 850-059 | 500-005 | 603-022 | 641-178 | 641-180 | | | 8 733 800 259 | | 601-009 | |
| | TW122-1CSC | 8 733 902 232 | | 641-216 | 562-033 | 860-006 | 700-047 | 601-001 | 8 733 902 041 | 850-059 | 500-005 | 603-022 | | 641-180 | 604-005 | | | 8 733 800 260 | | 601-009 |
| TW122-1CSN | 8 733 902 232 | | 641-216 | 562-033 | 860-006 | 700-047 | 601-001 | 8 733 902 042 | 850-059 | 500-005 | 603-022 | | 641-180 | 604-005 | | | 8 733 800 260 | | 601-009 | |
| Chiller Unit Mounted Control | TW025-1USC | 105-489 | | 641-179 | 562-032 | 860-005 | 700-018 | 601-040 | 300-223 | 850-060 | 500-037 | 603-022 | 641-178 | 641-180 | | | | | 641-190 | 601-009 |
| | TW025-1USN | 105-489 | | 641-179 | 562-032 | 860-005 | 700-018 | 601-040 | 300-224 | 850-060 | 500-037 | 603-022 | 641-178 | 641-180 | | | | | 641-190 | 601-009 |
| | TW035-1USC | 105-413 | | 641-179 | 562-032 | 860-005 | 700-025 | 601-040 | 300-225 | 850-061 | 500-037 | 603-022 | 641-178 | 641-180 | | | | | 641-190 | 601-009 |
| | TW035-1USN | 105-413 | | 641-179 | 562-032 | 860-005 | 700-025 | 601-040 | 300-226 | 850-061 | 500-037 | 603-022 | 641-178 | 641-180 | | | | | 641-190 | 601-009 |
| | TW049-1USC | 105-414 | | 641-179 | 562-032 | 860-006 | 700-027 | 601-007 | 300-133 | 850-062 | 500-006 | 603-022 | 641-178 | 641-180 | | | | | 641-190 | 601-009 |
| | TW049-1USN | 105-414 | | 641-179 | 562-032 | 860-006 | 700-027 | 601-007 | 300-132 | 850-062 | 500-006 | 603-022 | 641-178 | 641-180 | | | | | 641-190 | 601-009 |
| | TW061-1USC | 105-415 | | 641-216 | 562-033 | 860-006 | 700-047 | 601-001 | 300-128 | 850-059 | 500-005 | 603-022 | 641-178 | 641-180 | | | | | 641-190 | 601-009 |
| | TW061-1USN | 105-415 | | 641-216 | 562-033 | 860-006 | 700-047 | 601-001 | 300-129 | 850-059 | 500-005 | 603-022 | 641-178 | 641-180 | | | | | 641-190 | 601-009 |
| | TW071-1USC | 105-490 | | 641-216 | 562-033 | 860-006 | 700-047 | 601-001 | 300-130 | 850-059 | 500-005 | 603-022 | 641-178 | 641-180 | | | | | 641-190 | 601-009 |
| | TW071-1USN | 105-490 | | 641-216 | 562-033 | 860-006 | 700-047 | 601-001 | 300-131 | 850-059 | 500-005 | 603-022 | 641-178 | 641-180 | | | | | 641-190 | 601-009 |
| | TW122-1USC | 8 733 902 232 | | 641-216 | 562-033 | 860-006 | 700-047 | 601-001 | 8 733 902 041 | 850-059 | 500-005 | 603-022 | | 641-180 | 604-005 | | | | 641-190 | 601-009 |
| TW122-1USN | 8 733 902 232 | | 641-216 | 562-033 | 860-006 | 700-047 | 601-001 | 8 733 902 042 | 850-059 | 500-005 | 603-022 | | 641-180 | 604-005 | | | | 641-190 | 601-009 | |

